_	_		
	_	v	1

COUNTRY <u>East Germany</u>	ag agaga jinagagan parawayan pada daga kalada da sa kasan da da da da kasan da d	REPORT		
TOPIC Tutow Airfield	M demonstration in the second state of the second state of second state of the second		CT MAY AREA (FRO MICHAEL PROST), I MAN ANN ANN ANN ANN ANN ANN ANN ANN ANN	
	and which will be a supplied to the control of the	. January - Janu	CONTROL NO SEPTEMBRA ANTINOS ESTA SENSO ANTINOS ANTINO	
EVALUATION	PLACE OBTAINED			 25 <b>X</b> 1
DATE OF CONTENT.			Beautiful (September 200)	
DATE OBTAINED	DATE PREPA	RED19	March 1954	
REFERENCES				· www.yearners.elemp
PAGESENCLOSURE				· ARLEMONIA ARTON
the second secon	S (NO. & TYPE)		CXTender-date-milicartic Extlinitions rains rust i matemas sum	
PAGESENCLOSURE	S (NO. & TYPE)	i in the state of	CXTender-date-milicartic Extlinitions rains rust i matemas sum	
PAGESENCLOSURE	S (NO. & TYPE)	in the start of experience and the start design of the start of the st	CXTender-date-milicartic Extlinitions rains rust i matemas sum	

- 1. 487 workers of the Bauunion Brandenburg 25X1 were employed at Tutow airfield on 30 January 1954.
- 2. In February 1954, 400 to 500 workers of the Bauunion Brandenburg were employed at the sirfield. The former two landing fields were combined into one airfield and the wooded area between the two sections was cleared and graded. Formerly, a large pertion of the quartering buildings had been located in the wooded area. Low wooden quartering buildings for the non-local workers and a fire department were being erected at the field. Construction work was supervised by Soviet Air force officers.
- 3. In February, work had not been completed on the concrete runway which extends from north-northwest to south-southeast. Concreting work had been in full swing until the frost period. During the frost period, the workers were engaged in cleaning and grading work.
- 4. The airfield was surrounded by a board fence along the railroad line between Tutow and Krukow railroad stations. Poles, apparently for an additional board fence, had been put into the ground from the Krukow railroad station toward the northwest along the western side of the field. The guardhouse, occupied by factory police, was located in the southwestern section of the field. When compared with its previous location, it had been shifted 50 to 100 meters farther to the east, thus leaving Krukow railroad station outside of the fence.
- 5. The motor vehicles at the field were refueled from barrels in the fuel dump in the southern section of the field, about 400 meters south-southeast of the guardhouse. About 400 meters east of the guardhouse were two fuel containers, each about 7 meters long and 2.5 meters in diameter. Four additional containers arrived at the end of February.
- Of the former hangars only one was available; this serviceable hangar was used as storage shed for cement.
- 7. Excavation work was under way at the southeastern edge of the Alt Plastlin mode. The workers employed there said that aircraft dispersal areas would be constructed there.

Comment. The information indicates that the Bauunion Brandenburg has made little progress at Tutow airfield (referred to as Construction Project V 103). More intensive activity is expected to be made after the end of the frost period.

TATE BY SHEER STREET FORD, - U.S. OFFICIALS ONLY

25X1